

Select rings Capped bolt Operating panel Shaft pin

Round head screws

Truss head screws

Top cover

Stud bolt

Screw hole

Connectors


Arm


- Micro switch terminal
- 電源ランプ **⊕** ≠− ❷ ロック解除スイッチ 9 インジケーター (手動用スイッチ) ● ホイール
- ❸ キースイッチ ● セレクトピン
- ◆ ヒューズホルダー ❸ 間隙
- ホイール 6 電源プラグ ❷ 操作パネル ₩ カス受 🚯 丸ビス
- スタッドボルト ゆ セレクトレバー


● トップカバー


の アーム


- 🛛 ネジ穴 ₫ トラスネジ **4** コネクター
- 4ヤップボルト
- ❷ シャフトピン
- ❷ マイクロスイッチ端子











# 5. Changing Die-block (Refer to illustrations 1, 5)

IIIus. 1 ⊠-1

Remove the Power plug 6 from AC outlet before exchanging the Die-block.

- ▶ Dismounting
- Release four Round-head screws 6 to remove Operating panel 6.
- 📵 Remove Capped bolt 🚳 .
- 3 Remove two Connectors @ from the Micro switch terminal @
- Remove by pulling out Die-block toward you.
- ▶ Mounting
- Connect two Connectors (a) to Micro switch terminal (a).
- 2 Because the Shaft pin 3 is held down by the weight of the select ring unit, lift the unit up by grasping both ends of the Shaft pin when mounting. Otherwise the Shaft pin will not match Arm notches.
- 📵 Ease Shaft pin 🚳 into the Arm 🚳 notch, fit the rear notch of the Die-block into the Stud bolt 🚯, firmly tighten the Capped bolt @ to the Screw hole ...

## **6. Maintenance** (Refer to illustrations 5, 6)

- Power plug should be disconnected in advance from AC outlet.
- The main moving components require no lubrication due to the employment of needle bearings, etc. Other moving components are also specially surface-treated, and are given sufficient lubrication at the time of assembly, however, lubricated oil may become exhausted due to frictional heat, which will increase abrasion and shorten the life of the machine (although it depends upon frequency of use). Occasional application of lubricating oil is recommended for preventive maintenance.
- 🔟 Remove four Truss head screws 🚳 , and lift the Top cover 🚳 upward. (Removal of Operating panel 🕲 and Die-block is not required.)
- 1 Adrop or two of lubrication oil (regular light machine oil) should be given to the points indicated by
- 🛐 Return the Top cover 🤀 to its original position, and tighten with four Truss head screws 🐠

### ≪Precautions

- ☐ If not used for a long period, turn off the Key switch ⑤ or disconnect the Power plug ⑥ from AC outlet;
- [7] In repeated perforating operation, the Paper waste receptacle @ will overflow. Empty periodically.

- 3 2個のコネクターのをマイクロスイッチの端子のから外す。
- 4 ダイブロックを手前に引き出す。

#### ▶取り付け方法

- 1 2個のコネクター◆をマイクロスイッチの端子◆に接続する。
- 2 ホイール部の自重でシャフトピン❸がさがっていますので、シャフトピンの両端をもってホイール部をあげ
- ③ シャフトピン❷をアーム●の切欠に合せ、ダイブロック後部切欠をスタッドボルト●に入るように押し込み ネジ穴●にキャップボルト❷を締め付け固定します。

## 6. 保守(図-5、図-6参照)

- ※ 電源プラグ●をコンセントから抜いてから行って下さい。
- ※ 主要摺動部分にはニードルベアリング等を用いてありますので、注油の必要はありません。ほかの摺動部分 にも特殊表面処理を施こし、組立時には注油もしてありますが、摩擦等による熱で油が蒸発してしまいます と摩耗が早くおこり、機械の寿命を縮めてしまいます(使用頻度によって異なります)ので、適時注油をして
- □ トラスネジ@を4本外し、トップカバー®を上方に持ち上げます。(操作バネル®とダイブロックは外す必 要はありません。)
- 2 若干の油(ミシン油で可)を矢印(→)の部分に適量注油して下さい。
- 3 トップカバー●を元の位置におさめ、トラスネジ@を4本締め付けて下さい。

# 《ご使用上の注意》

- □ 長時間ご使用にならない時はキースイッチ®を切るか電源プラグ®をコンセントから抜いて下さい。
- ② 打抜操作を繰り返しますとカス受命に紙カスがたまります。あまり紙カスがたまらないうちに捨てて下さい。